KIT 404 - MOD KIT-THROTTLE PEDAL

1. PREPARATION

- 1.1. Park machine on firm level ground and apply parking brake.
- 1.2. Place in neutral, stop engine and remove ignition key.
- 1.3. Switch battery Isolator to 'OFF'
- 1.4. Remove floor mat (Cab machines only)
- 1.5. Remove floorplate(s).

2. PRE-ASSEMBLY

- 2.1. Remove treadle pad from throttle pedal (107621), retain screws.
- 2.2. Fit throttle pedal treadle assembly (107520) to throttle pedal with existing screws.





2.3. Fit mounting plate (107465) to the pedal assembly with socket c/sunk head screw (16473) 3 off.



- 2.4. Fit throttle stop (107522) to shield plate (107521) and secure with plain washer (13911) and nyloc nut (16481).
- 2.5. Set so that the of the set screw head (7465) is 36mm from the top of the shield plate, secure lock nut (9775).







3. REMOVE THROTTLE PEDAL FROM MACHINE.

- 3.1. Remove the 6 fixings holding the throttle pedal, discard.
- 3.2. Feed throttle pedal down through the hole in the leg guard.






- 3.3. Disconnect harness plug from throttle pedal.
- 3.4. Discard throttle pedal.



4. CHANGE THROTTLE CONNECTOR ON THE VEHICLE HARNESS.


IMPORTANT - When cutting the wires **ONLY CUT ONE WIRE AT A TIME!** Crimp a terminal supplied onto the wire, then insert the terminal/wire into the correct cavity of the Deutsch connector supplied **BEFORE CUTTING THE NEXT WIRE!**


- 4.1. Parts required from kit.
- 4.2. Fit the cavity plug supplied in the service kit into cavity `5' of the Deutsch connector supplied.






4.3. On the vehicle harness, throttle pedal connector (marked C021), on the top side of the connector you will see the cavities are named from left to right `A-F'.






- 4.4. Starting with the wire in cavity `A', cut the wire.
- 4.5. Remove @4-5mm of insulation from the wire.
- 4.6. Crimp a terminal supplied to the stripped wire.
- 4.7. Insert the crimped terminal/wire into cavity `1' of the Deutsch connector.










4.8. Repeat this process with the wires from cavities B, C, D, F, inserting each crimped terminal/wire into the Deutsch connector supplied, into cavities 2, 3, 4, 6 respectively.

REMEMBER-Complete one wire before cutting the next!

4.9. Once all five terminals/wires are inserted into the Deutsch connector, insert the wedgelock to lock the terminals into position.





5. FIT THROTTLE PEDAL ASSEMBLY.

- 5.1. Connect the sub-harness (107636) to throttle pedal assembly.
- 5.2. Feed the throttle pedal assembly up through the hole in the leg guard.





- 5.3. Secure in 2 diagonal locations as shown with set screws (16476), spring washers (14837) and heavy duty washers (15830).
- 5.4. Connect harness plug to throttle pedal sub-harness.






6. PEDAL SHIELD ASSEMBLY

STANDARD MACHINES

- 6.1. Fit pedal shield assembly to leg guard with 4 set screws (16476), spring washers (14837) and heavy duty washers (15830).
- 6.2. Refit floorplate.



CAB MACHINES

- 6.3. Turn floor mat over and cut out the 4 holes shown.
- 6.4. Place pedal shield assembly on to leg guard.
- 6.5. Refit floorplates.





- 6.6. Refit floor mat, ensure pedal shield assembly remains in place.
- 6.7. Place the 4 spacers (107549) in the holes in mat.
- 6.8. Fit throttle pedal cover (107547) to leg guard with 4 set screws (17155), spring washers (14837) and heavy duty washers (15830) ensure all plates and spacers in line.





7. **COMPLETION**

7.1. Switch battery Isolator to 'ON'

Parts List

107621	Throttle pedal - Curtis	1 off
107520	Throttle Pedal Treadle	1 off
107465	Throttle Pedal Mount	1 off
16473	Socket C/Sunk Head Screw	3 off
107522	Throttle Stop	1 off
13911	Washer	1 off
16481	Nyloc Nut	1 off
7465	Set Screw	1 off
9775	Nut	1 off
107521	Pedal Shield	1 off
107636	T4 Sub-harness Throttle Curtis	1 off
14837	Spring Washer	6 off
15830	Heavy Duty Washer	6 off
54824	Deutsch 6-way socket housing	1 off
54825	Deutsch Wedgelock	1 off
54826	Deutsch socket terminal	5 off
54827	Deutsch cavity plug	1 off
16476	Set Screw	6 off

CAB ONLY

107547	Pedal Cover	1 off	
107549	Spacer	4 off	
17155	Bolt	4 off	

C021 THROTTLE PEDAL

						Destination	Multicore ID
Α	69	TS/80	0	0.75		C046-63	
В	70	TS/85	0	0.75	75	SP6-X	
С	71	TS/81	0	0.75		C046-46	
D	72	TS/79	0	0.75		C046-16	
Ε	73						
F	73	TS/86	0	0.75		SP6-X	

Connector: 1:12162210

Term Socket 1-2mm Metripack : 5 : 12124075 BLANK : 1 : 12065266

